Signature:



knowing violations

TENNESSEE DEPARTMENT OF TRANSPORTATION EROSION PREVENTION/SEDIMENT CONTROL INSPECTION REPORT

Reason For Inspection:

1st Weekly

2nd Weekly

State Roule (SR) / US Roule or Road Name and Description: Are corrective actions required by this inspection report (Y/N): Wolf River Blvd. County(ies): TOOT PIN: NPDES Permit (NOC) #: Number of New Number of Recurring Number of New Number of Un-Corrected Corrective Actions: Corrective Actions: Sediment Releases: Sediment Releases: Shelby 101615 TNR153299 TDOT Construction No. TDOT Contract No.: Contractor: 7994-1535-54 Acuff Enterprises Inc. I certify, under penally of law that this document and all attachments were COG EPSC Inspector and Title (print or type): Signature: prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated Gerald "Jerry" Stanfill information presented. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the Contractor EPSC Inspector and Title (print or type): information, I cerify that inspections of storm water discharge points (outfalls), and Signature: of erosion and sediment controls have been performed as recorded in the table above. I certify that erosion and sediment controls in the drainage area of the Tom Acuff identified outfall where installed as planned and designed in working order as

COG EPSC Project Manager

Timothy Bierdz

TDOT EPSC Inspection Weakly Painfall Data Lan

	r	TDOT EPSC	Inspectio	n Weekly F	Rainfall Dat	a Log				()
		Predicted	Rainfall	Rainfall	Rainfall	Rainfall	Rainfall	Rainfall		TDOT/Contractor Agrees with Inspection Report:
Date .	Day of Week	Precipitation	Gauge 1	Gauge 2	Gauge 3	Gauge 4	Gauge 5	Gauge 6	Duration	NO or YES
		(%)	(in)	(in)	(in)	(in)	(in)	(in)	(hr)	If No, explain and initial:
	Sunday				N/A	N/A	N/A	N/A		Que to wet working conditions
11/28/11	Monday	70	2.02	2,00	N/A	N/A	N/A	N/A	60	corrections can (not be mad
11/29/11	Tuesday	20			N/A	N/A	N/A	N/A		at this temp.
11/30/11	Wednesday	0			N/A	N/A	N/A	N/A		
12/1/11	Thursday	1:0			N/A	N/A	N/A	N/A		
11/25/11	Friday	6	0	٥	N/A	N/A	N/A	N/A		
11/26/11	Saturday	40			N/A	N/A	N/A	N/A		
11/27/11	Sunday	50			N/A	N/A	N/A	N/A		
	Monday				N/A	N/A	N/A	N/A		
								<u> </u>		(Additional pages may be attached, if needed)

Predicted Precipitation Source:

recorded in the table above. I am aware that there are significant penalties for

submitting false information, including the possibility of fine and impresonment for (print or type):

www.weather.com

Page 1 of 6

وننزو	STHE	37
	GRICUL	LURE -
	A A	
1/4	7796	33/

State/US Route or Road Name:	Wolf River Blvd.	TDOT Construction No.:	79954-3537-54	TDOT Contract No.:

Date	11/28/2011	

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
1	1	14+14	LT	11/17/2011		22,35	w	Weekly cleaning will be required, until further notice.
1A	1	21+50	RT	11/17/2011		41	w	Const. of RCBC Pedestrian Underpass in progress.
1B	1	22+00	RT	11/10/2011		41	W	No activity during this inspection. BMP's required.
1C	1	21+00	LT	11/7/2011	T = 10-6-11	12,15,35,41	W	Monitoring BMP's in place.
2A	1	33+50	LT,CL	11/17/2011		12,15,16,24	w	Monitoring BMP's in place.
2B	1	35+50	LT	11/17/2011	= = = = = = = = = = = = = = = = = = = =	16,24	W	Weekly cleaning for stream crossing required, until further notice.
3	1	34+50	LT	10/27/2011		16	w	Monitoring BMP in place.
4	1	40+00	RT	11/7/2011	T = 10-24-11	15,16,43	ı	Repair wash out area. See 11-25-11 report for photo.
5A	1	49+00	RT	10/24/2011		16,33	1	Sediment removal required. See 11-25-11 report for photo.
5B	1	50+00	RT	10/24/2011		9,16,33	ı	Increase section of temp. sedement basin. See 11-25-11 report for photo.

EROSION AND SEDIMENT CONTROL MEASURE CODES

1	Temporary Silt Fence / Filter Barrier	15	Temporary seeding with Mulch	29	Excess Dirt Removed from Rdwy. Daily	M	Maintenance
2	Temporary Diversion Berm or Ditch	16	Temporary Mulch	30	Haul Roads Dampened for Dust Control	U	Upgrade Needed (Failure Noted)
3	Temporary Slope Drain	17	Erosion Control Blanket	31	Ditch Liner	R	Replacement Needed
4	Rock Check Dams	18	Flexible Channel Liner	32	Rock Silt Screen	FM	Future Maintenance
5	Brush Barrier	19	Catch Basin / Storm Inlet Protection	33	Temporary Silt Fence with Backing	С	Cleaning Needed
6	Sediment Removal	20	Riprap Outlet Structure	34	Enhanced Silt Fence	1	Increase Measures
7	Straw Bale Check	21	Riprap Energy / Velocity Dissipater	35	Sediment Tube	W	Too Wet to Work Conditions
8	Sand Bags	22	Curb, Gutter, or Storm Sewer Protection	36	Sediment Dam	RO	Repeat Occurrence
9	Sediment Trap / Basin	23	Temporary at Construction Exit / Entrance	37	Concrete Washout, other pollution Issues	SR	Sediment Release
10	Temp Sediment Filter Bag / Dewatering	24	Temporary Stream Crossing	38	Berm (soil, riprap, rock)	FS	Final Stabilized
11	Polyethylene Sheeting	25	Turbidity Barrier / Silt Boom	39	Gabion	S	Stable (No Action Needed)
12	Machined Rip Rap	26	Temporary Stream Diversion	40	Sheet Pilling	Other (O31):	
13	Geotextile	27	Preserve Natural Resource / Buffer Zone	41	Haul Road	Other (O#2):	
14	Permanent Seeding with Mulch or Sod	28	Mineral Aggregate Base on Subgrade	42	Bridge Construction	Other (O#3):	
				43	Stream Realignment		

CONDITION CODES

State/US	Route	or	Road	Name

Wolf I	River	Blvd.
--------	-------	-------

TDOT Construction No.: 79954-3537-54

TDOT Contract No.:

Date

11/28/2011

			T		100000000000000000000000000000000000000			
Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
5C	1	44+00	LT	11/17/2011		16,24,33	1	Weekly cleaning for stream crossing required. A section of BMP's needs to be completed along top of north and south bank @ New Channel Realignment. See 11-25-11 report for photo.
6	1	56+00	LT	10/24/2011			W	Pond to be re-drained at a future date. Currently Stable.
7	1	60+00	RT	10/24/2011		16, 33	w	Currently Stable, Monitoring BMP's.
8A	1	73+00	RT	11/17/2011		16,24,42	W	Weekly cleaning for stream crossing will be required, until further notice.
8B	2	75+50	RT	9/29/2011		16,24,35,41	W	Currently Stable, Monitoring BMP's.
8C	1	71+00	LT	11/17/2011		16,35,42	W	Active construction zone. Monitoring BMP's.
8D	2	75+50	LT	10/3/2011	T = 10-3-11	16,35,42	W	Monitoring BMP's. Weekly watering required until seed establishes.
8E	1	71+50	LT					The area has not been disturbed.
9A	2	80+00	RT	9/29//11	T = 10-3-11	6,15,33,35	W	Weekly watering required until seed establishes.
9B	2	80+00	LT	9/29//11	T = 10-3-11	15,16,17,,35	W	Weekly watering required until seed establishes.

EROSION AND SEDIMENT CONTROL MEASURE CODES

Temporary Silt Fence / Filter Barrier Temporary Seeding with Mulch 29 Excess Dirt Removed from Rdwy. Daily Maintenance M Temporary Diversion Berm or Ditch 2 Temporary Mulch 30 Haul Roads Dampened for Dust Control Upgrade Needed (Failure Noted) U 3 Temporary Slope Drain 17 **Erosion Control Blanket** 31 Ditch Liner R Replacement Needed Rock Check Dams 4 18 Flexible Channel Liner 32 Rock Silt Screen FΜ Future Maintenance 5 Brush Barrier 19 Catch Basin / Storm Inlet Protection 33 Temporary Silt Fence with Backing C Cleaning Needed 6 Sediment Removal 20 Riprap Outlet Structure 34 Enhanced Silt Fence Increase Measures 7 Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions 8 Sand Bags 22 Curb, Gutter, or Storm Sewer Protection Sediment Dam 36 RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release 10 Temp Sediment Filter Bag / Dewatering 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) FS Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 Gabion s Stable (No Action Needed) Machined Rip Rap Other (O31): 12 26 Temporary Stream Diversion 40 Sheet Pilling 13 Geotextile 27 Preserve Natural Resource / Buffer Zone 41 Haul Road Other (O#2): Permanent Seeding with Mulch or Sod Mineral Aggregate Base on Subgrade **Bridge Construction** Other (O#3):

CONDITION CODES

State/	US	Rout	e or	Road	Name

Wolf River Blvd.

TDOT Construction No.:

79954-3537-54

TDOT Contract No.:

Date	11/28/2011

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
9C	2	79+50	LT	9/29/2011	T = 10-03-11	15,16,20,33	W	Weekly watering required until seed establishes.
10A	2	85+00	RT	9/29/2011		15,16,35,41	w	Monitoring BMP's in place.
10B	2	85+00	RT	9/29/2011		15,16,35,41	w	Monitoring BMP's in place.
10C	2	85+50	LT	11/14/2011		15,16,35,41	w	BMP's are required. See Photo
10D	2	84+50	LT	11/14/2011		15,16,35,41	w	BMP's are required. See Photo
11A	2	92+50	RT	11/14/2011		35,41	w	Monitoring BMP's in place.
11B	2	92+50	LT	10/6/2011		10,32,35,41	w	Remove forms when accessible.
11C	2	92+00	LT	10/6/2011		10,32,35,41	W	Remove forms when accessible.
1985-17	1	11+28	LT	11/17/2011		19,35	w	Daily cleaning is required, until further notice.
	1	13+40	RT	11/17/2011		23,29,30	W	Daily cleaning will be required, until further notice.
	1	107+75	CL	11/17/2011	MEASURE CODES	23,29,30	W	Daily cleaning will be required, until further notice. CONDITION CODES

EROSION AND SEDIMENT CONTROL MEASURE CODES

Temporary Silt Fence / Filter Barrier 15 Temporary Seeding with Mulch 29 Excess Dirt Removed from Rdwy. Daily M Maintenance 2 Temporary Diversion Berm or Ditch 16 Temporary Mulch 30 Haul Roads Dampened for Dust Control Upgrade Needed (Failure Noted) Temporary Slope Drain 3 17 **Erosion Control Blanket** 31 Ditch Liner R Replacement Needed 4 Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen FM Future Maintenance Brush Barrier 5 19 Catch Basin / Storm Inlet Protection 33 Temporary Silt Fence with Backing C Cleaning Needed Sediment Removal 6 20 Riprap Outlet Structure 34 **Enhanced Silt Fence** Increase Measures 7 Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions 8 Sand Bags 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues Sediment Release SR Temp Sediment Filter Bag / Dewatering 10 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) FS Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) 12 Machined Rip Rap 26 Temporary Stream Diversion 40 Sheet Pilling Other (O31): 13 Geotextile 27 Other (O#2): Preserve Natural Resource / Buffer Zone 41 Haul Road 14 Permanent Seeding with Mulch or Sod 28 Mineral Aggregate Base on Subgrade **Bridge Construction** Other (O#3):

	OF THE ST	
6		1
	CRICOFICKE	
1/3	1796 - 3	

State/US Route or Road Name:	Wolf River Blvd.	TDOT Construction No.:	79954-3537-54	TDOT Contract No.:	

Date	11/28/2011

Outfall Name or Station No. *(Existing Structure)	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments	
* 109+51	2	East side of WRB	RT	11/17/2011	P - Peilli.	19,22	w	Daily cleaning will be required, until further notice.	
* 109+11	2	South side of Farmington	RT	11/17/2011		19,22	w	Daily cleaning will be required, until further notice.	
* 12+80	1	North side of WRB	LT	11/17/2011		19,22	W	Daily cleaning will be required, until further notice.	
	1	Walking Trail 36+00	LT	7/20/2011	T = 7-20-11	5,35	w	Currently stable, Monitoring BMP's	
	1	Sta. 29+50 Slope	LT	7/20/2011	T= 9-01-11	16	w	Currently stable.	
		Sta. 13+40 - Sta. 107+75	LT, RT or CL	10/13/2011		30	w	Haul roads dampened frequently for dust control, until further notice.	
	2	76+50 - 103+46	RT	9/29/2011	T = 10-03-11	15,16,35	w	Weekly watering required until seed establishes.	
	2	92+50 - 107+00	LT	9/29/2011	T = 10-03-11	15,16,35	w	Weekly watering required until seed establishes.	
	1	6+75	LT	11/17/2011	200	19,22	W	Daily cleaning will be required, until further notice.	
	1	27+00	RT	10/3/2011	T= 10-03-11	15,16	W	Currently stable, Monitoring BMP's	
1 34+00 RT 8/25/2011 T= 8-25-11 16 W Currently stable, Monitoring BMP's EROSION AND SEDIMENT CONTROL MEASURE CODES CONDITION CODES									

EROSION AND SEDIMENT CONTROL MEASURE CODES

							CONDITION CODEC
1	Temporary Silt Fence / Filter Barrier	15	Temporary Seeding with Mulch	29	Excess Dirt Removed from Rdwy. Daily	М	Maintenance
2	Temporary Diversion Berm or Ditch	16	Temporary Mulch	30	Haul Roads Dampened for Dust Control	U	Upgrade Needed (Failure Noted)
3	Temporary Slope Drain	17	Erosion Control Blanket	31	Ditch Liner	R	Replacement Needed
4	Rock Check Dams	18	Flexible Channel Liner	32	Rock Silt Screen	FM	Future Maintenance
5	Brush Barrier	19	Catch Basin / Storm Inlet Protection	33	Temporary Silt Fence with Backing	С	Cleaning Needed
6	Sediment Removal	20	Riprap Outlet Structure	34	Enhanced Silt Fence	I	Increase Measures
7	Straw Bale Check	21	Riprap Energy / Velocity Dissipater	35	Sediment Tube	W	Too Wet to Work Conditions
8	Sand Bags	22	Curb, Gutter, or Storm Sewer Protection	36	Sediment Dam	RO	Repeat Occurrence
9	Sediment Trap / Basin	23	Temporary at Construction Exit / Entrance	37	Concrete Washout, other pollution Issues	SR	Sediment Release
10	Temp Sediment Filter Bag / Dewatering	24	Temporary Stream Crossing	38	Berm (soil, riprap, rock)	FS	Final Stabilized
11	Polyethylene Sheeting	25	Turbidity Barrier / Silt Boom	39	Gabion	S	Stable (No Action Needed)
12	Machined Rip Rap	26	Temporary Stream Diversion	40	Sheet Pilling	Other (O31):	
13	Geotextile	27	Preserve Natural Resource / Buffer Zone	41	Haul Road	Other (O#2):	
14	Permanent Seeding with Mulch or Sod	28	Mineral Aggregate Base on Subgrade	42	Bridge Construction	Other (O#3):	

EPSC Inspection

OF THE ST
APA .
AGRICUITURE
1796

0 id Name:	Wolf River Blvd.	TDOT Construction No.:	79954-3537-54	TDOT Contract No.:

Date 11/28/2011

Outfall Name	Dei		. T DT	5	Date of	Existing	120	
Outfall Name or Station No.	Rain Gage	Approx. Station No.	LT, RT or Centerline	Date Last Disturbed	Stabilization	EPSC	Current	
or Station No.	No.	From / To	Centenine	Disturbed	and Code T = Temp.	Control	Condition	Corrective Action(s) or Comments
	140.	110111710			P = Perm.	Measure Codes*	Codes*	
					r - reiiii.	Codes		Weekly watering required until seed
	1	21+33 - 26+00	LT	10/10/2011	T = 10-6-11	15,16,35,41	W	establishes.
								Weekly watering required until seed
	1	21+33 - 26+00	RT	10/10/2011	T = 10-6-11	15,16,35,41	W	establishes.
	4	25+00	I.T.	0/20/2044	T - 40 C 44	45 40 00 05 44	107	2 4
	- 1	25+00	LT	9/29/2011	T = 10-6-11	15,16,33,35,41	W	Currently stable, monitoring BMP's.
	4	25+00	RT	9/29/2011	T = 10-6-11	45 40 00 05 44	107	O II . I I
	'	23+00	KI .	9/29/2011	1 = 10-6-11	15,16,33,35,41	W	Currently stable, monitoring BMP's.
	1	27+50	RT	10/6/2011	T = 10-6-11	15,16,33,35,41	W	Currently stable, monitoring BMP's.
	4	31+90	RT	0/00/0044	T 40 0 44	45.40.05		
		31+90	K1	9/29/2011	T = 10-6-11	15,16,35	W	Currently stable, monitoring BMP's.
	1	15+60	RT	9/15/2011	T = 10-6-11	15,16,33,35	W	Currently stable, monitoring BMP's. Weekly watering required until seed establishes.
		North side of						Daily cleaning will be required, until further
* 108+37		WRB	LT	11/17/2011	•	19,22	W	notice.
	1	23+00 - 26+00	RT	9/29/2011	T = 10-6-11	33,41	W	Currently stable, monitoring BMP's.
					No. 10.			

EROSION AND SEDIMENT CONTROL MEASURE CODES

1	Temporary Silt Fence / Filter Barrier	15	Temporary Seeding with Mulch	29	Excess Dirt Removed from Rdwy. Daily	М	Maintenance
2	Temporary Diversion Berm or Ditch	16	Temporary Mulch	30	Haul Roads Dampened for Dust Control	U	Upgrade Needed (Failure Noted)
3	Temporary Slope Drain	17	Erosion Control Blanket	31	Ditch Liner	R	Replacement Needed
4	Rock Check Dams	18	Flexible Channel Liner	32	Rock Silt Screen	FM	Future Maintenance
5	Brush Barrier	19	Catch Basin / Storm Inlet Protection	33	Temporary Silt Fence with Backing	С	Cleaning Needed
6	Sediment Removal	20	Riprap Outlet Structure	34	Enhanced Silt Fence	1	Increase Measures
7	Straw Bale Check	21	Riprap Energy / Velocity Dissipater	35	Sediment Tube	w	Too Wet to Work Conditions
8	Sand Bags	22	Curb, Gutter, or Storm Sewer Protection	36	Sediment Dam	RO	Repeat Occurrence
9	Sediment Trap / Basin	23	Temporary at Construction Exit / Entrance	37	Concrete Washout, other pollution Issues	SR	Sediment Release
10	Temp Sediment Filter Bag / Dewatering	24	Temporary Stream Crossing	38	Berm (soil, riprap, rock)	FS	Final Stabilized
11	Polyethylene Sheeting	25	Turbidity Barrier / Silt Boom	39	Gabion	S	Stable (No Action Needed)
12	Machined Rip Rap	26	Temporary Stream Diversion	40	Sheet Pilling	Other (O31):	
13	Geotextile	27	Preserve Natural Resource / Buffer Zone	41	Haul Road	Other (O#2):	
14	Permanent Seeding with Mulch or Sod	28	Mineral Aggregate Base on Sub grade	42	Bridge Construction	Other (O#3):	10 - 10 - 10 - 10 - 10 - 10 - 10 - 10 -

CONDITION CODES